


2025

FIG. 1(a)

FIG. 2



00374235 060401
104090 SEETZ 2550

FIG. 3(a)




FIG. 3(b)




FIG. 4





FIG. 5



00074335.060401

FIG. 6




FIG. 7




FIG. 8




FIG. 9





FIG. 10






FIG. 11

A. STENTS OVER DELIVERY SYSTEM
(NOT DEPLOYED)




FIG. 12

B. STENTS ALONE
(NOT DEPLOYED)




FIG. 13

C. STENTS EXPANDED




FIG 14

D. ONE STENT LAYOUT

- Side Access.
- BIF.

FIG 15




FIG 16





FIG.

10





fig. 19

